	FORM F PREVIOUS 5-43 - PRITIONS	13		MFG. 9-66				
27.	Approved For Release 200	3/41/25 : CIA-ROP69B000 S E C R E T	41R00080001	0026-2				
· ·	DATE	2 3	and the state of t	10				
162 360	And the control of th	A S	An Bradis allek dire som derfyret. De egen in 't eget en til delekskadigk gang eingbygg An An A	12				
• 1	ro .	6	معدد المحدد ا وقال المحدد	13 14 15				
F	ROM :	¥ 1 × 1 × 1 × 1 × 1 × 1 × 1 × 1 × 1 × 1	Carpothylarina (perdiamental, e/C maks, etc.p. maks), in color parathles estimated in color parathles e					
1	ACTION:							
1	NFO :	A service of	CAMPBO STANS STANS TO SEE STANS STANS	So.T.E.				
:	IN: 55403	OSA 45	0	OSI OCTZCH				
25X1 ^{T(}	O INFO	*	CITE	The second secon				
25X1	TOPSECRET 041102Z CITE	.						
	PRIORITY	10 B						
25X1								
25X1	GENERAL BACALIS FROM	± 14 × 1						
25X1	APPEARED TO HAVE A	GOOD MISSION. REP	ORTING, G	ENERATION,				
	DEPARTURE AND RECOVERY ALL WEN	T AS PROGRAMED.						
	2. ROUTE WAS FLOWN AS BRIE	FED ALTHOUGH PILOT	WAS CAUT	IONED				
	TO PLAY THE FUEL CONSERVATIVEL	Y BECAUSE OF QUEST	IONABLE R	ECOVERY				
25X1	WEATHER AT ARTICLE FILLED TO BETTER THAN 67,000 ON EACH							
	AIR REFUELING AND WITH STABLE	COOL TEMPERATURES	ALOFT CUR	VES WERE				
	EXCELLENT. PILOT ENTERED DENI	ED ON FIRST PENETR	ATION AT	ABOUT				
	79.5M AND AT 78.0M ON THE SECO	ND. CITS REMAINED	ABOUT 37	Ø AT 3.1				
	TRUE KEEPING DOORS OPTIMIZED D	URING CRUISE.		•				
	3. WEATHER IN TARGET AREA	WAS APPROXIMATELY	AS FORECA	ST.				
	GOOD AND CLEAR IN THE HANOI AND	D HAIPHONG AREAS.	REALLY S	WEATING				
25X1	WEATHER AS IT INTERMIT	TENTLY WENT AS LOW	AS 300 F	EET AND				
	LESS THAN ONE MILE. HOWEVER,	BASE WAS IN GOOD S	HAPE FOR	RECOVERY.				
	4. PACKAGE APPEARED TO OPER	RATE AS ADVERTISED	. PILOT	ACTUALLY				
	T 0P S I	E C R E T	EXCLUDED FROM AUTO- NATIC DOWNGRADISH	0026-2				

	in the	~
		· •
25X1	INE	55403

25X1

Approved For Re	lease 2003	3/11	1/25	5 : 0	CIA	-RI	DP	69E	30004 4	B900800010026	-2
	T	0	p	S	E	C	R	E	T	PAGE 2	

TURNED CAMERA ON ONE MINUTE LATE DURING FIRST PASS BECAUSE ARTICLE WAS STILL IN BANK DUE TO SLIGHT OVERSHOOT; THIS IS STANDARD POLICY AS FAR AS CAMERA OPERATION IS CONCERNED. TOOK ABOUT 2500 FEET.

					•
~	A T D A D A C T	ELA CE	かいつかしし かんか	SA A W ALTO PU LI A ST MAN	1 1 10 10 10 10 10 10 10 10 10 10 10 10
5.	AIRIRANI	WAS	- P X (MAINTENANCE	111 100-11
~ •	Laws constant	41. 1.3		THE PART INTO THE	77 L, 4.7 Car &

- 7. A-50 STILL A MAJOR LOGISTICS PROBLEM BUT UNDERSTAND THE REASONING BEHIND AT LEAST GIVING IT A TRY. TANKERS ALMOST FORCED TO BURN A-50 IF THERE IS ANY DELAY BY RECEIVER. AND SAC STILL NOT AUTHORIZING USE EXCEPT IN EMERGENCY. DOWNLOADED APPROXIMATELY 450,000 POUNDS AND UPLOADED APPROX 550,000 POUNDS IN PREPARATION FOR TODAYS MISSION.
- 8. ANY CHANCE OF US SHOOTING THE GAP BETWEEN THE MAINLAND AND HAINAN IN THE NEAR FUTURE. AND STILL HOPING FOR A GO AT NK.
- 9. CHEERS AND WHEN DO WE HEAR FROM THE BIG COMMITTEES ON STATUS?

T O P S E C R E T TOR: 041125Z SEP 67

TOPSECRET

Next 1 Page(s) In Document Exempt